


Chapter 10:

Phase Transformations

ISSUES TO ADDRESS...

- Transforming one phase into another takes time.



- How does the rate of transformation depend on time and T ?
- How can we slow down the transformation so that we can engineering non-equilibrium structures?
- Are the mechanical properties of non-equilibrium structures better?

Phase Transformations

Nucleation

- nuclei (seeds) act as template to grow crystals
- for nucleus to form rate of addition of atoms to nucleus must be faster than rate of loss
- once nucleated, grow until reach equilibrium

Driving force to nucleate increases as we increase ΔT

- **supercooling** (eutectic, eutectoid)
- **superheating** (peritectic)

Small supercooling \rightarrow few nuclei - large crystals

Large supercooling \rightarrow rapid nucleation - many nuclei,
small crystals




Solidification: Nucleation Processes

- Homogeneous nucleation
 - nuclei form in the bulk of liquid metal
 - requires supercooling (typically 80-300°C max)
- Heterogeneous nucleation
 - much easier since stable “nucleus” is already present
 - Could be wall of mold or impurities in the liquid phase
 - allows solidification with only 0.1-10°C supercooling



Homogeneous Nucleation & Energy Effects



r^* = **critical nucleus**: nuclei $< r^*$ shrink; nuclei $> r^*$ grow (to reduce energy)



Solidification

$$r^* = \frac{-2\gamma T_m}{\Delta H_S \Delta T}$$

r^* = critical radius

γ = surface free energy

T_m = melting temperature

ΔH_S = latent heat of solidification

$\Delta T = T_m - T$ = supercooling

Note: ΔH_S = strong function of ΔT
 γ = weak function of ΔT

$\therefore r^*$ decreases as ΔT increases

For typical ΔT r^* ca. 100Å




Rate of Phase Transformations

Kinetics - measure approach to equilibrium vs. time

- Hold temperature constant & measure conversion vs. time
 - **How is conversion measured?**
 - X-ray diffraction – have to do many samples
 - electrical conductivity – follow one sample
 - sound waves – one sample



Rate of Phase Transformation



Adapted from
Fig. 10.10,
Callister 7e.

Avrami rate equation $\Rightarrow y = 1 - \exp(-kt^n)$

fraction
transformed

time


– k & n fit for specific sample

By convention

$$r = 1 / t_{0.5}$$



Rate of Phase Transformations



Adapted from Fig. 10.11, *Callister 7e*. (Fig. 10.11 adapted from B.F. Decker and D. Harker, "Recrystallization in Rolled Copper", *Trans AIME*, **188**, 1950, p. 888.)

- In general, rate increases as $T \uparrow$

$$r = 1/t_{0.5} = A e^{-Q/RT}$$

- R = gas constant
- T = temperature (K)
- A = preexponential factor
- Q = activation energy

Arrhenius
expression

- r often small: equilibrium not possible!




Eutectoid Transformation Rate


- Growth of pearlite from austenite:

Austenite (γ)
grain
boundary


Adapted from
Fig. 9.15,
Callister 7e.



Diffusive flow
of C needed



- Recrystallization rate increases with ΔT .




Adapted from
Fig. 10.12,
Callister 7e.

Course pearlite → formed at higher T - softer
Fine pearlite → formed at low T - harder


Nucleation and Growth

- Reaction rate is a result of nucleation and growth of crystals.




Adapted from
Fig. 10.10, Callister 7e.


- Examples:



T just below T_E
Nucleation rate low
Growth rate high



T moderately below T_E
Nucleation rate med
Growth rate med.



T way below T_E
Nucleation rate high
Growth rate low



Transformations & Undercooling

- **Eutectoid** transf. (Fe-C System):

- Can make it occur at:

...727°C (cool it slowly)

...below 727°C (“undercool” it!)




Adapted from Fig. 9.24, Callister 7e. (Fig. 9.24 adapted from *Binary Alloy Phase Diagrams*, 2nd ed., Vol. 1, T.B. Massalski (Ed.-in-Chief), ASM International, Materials Park, OH, 1990.)



Isothermal Transformation Diagrams

- Fe-C system, $C_o = 0.76 \text{ wt\% C}$
- Transformation at $T = 675^\circ\text{C}$.




Adapted from Fig. 10.13, Callister 7e.
(Fig. 10.13 adapted from H. Boyer (Ed.)
*Atlas of Isothermal Transformation and
Cooling Transformation Diagrams*,
American Society for Metals, 1977, p.
369.)



Effect of Cooling History in Fe-C System

- Eutectoid composition, $C_0 = 0.76 \text{ wt\% C}$
- Begin at $T > 727^\circ\text{C}$
- Rapidly cool to 625°C and hold isothermally.





Adapted from Fig. 10.14, Callister 7e.
(Fig. 10.14 adapted from H. Boyer (Ed.) *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, American Society for Metals, 1997, p. 28.)



Transformations with Proeutectoid Materials

$C_0 = 1.13 \text{ wt\% C}$





Hypereutectoid composition – proeutectoid cementite



Non-Equilibrium Transformation

Products: Fe-C

- Bainite:
 - α lathes (strips) with long rods of Fe_3C
 - diffusion controlled.
- Isothermal Transf. Diagram



(Adapted from Fig. 10.17, Callister, 7e. (Fig. 10.17 from *Metals Handbook*, 8th ed., Vol. 8, *Metallography, Structures, and Phase Diagrams*, American Society for Metals, Materials Park, OH, 1973.)


Adapted from Fig. 10.18, Callister 7e.

(Fig. 10.18 adapted from H. Boyer (Ed.) *Atlas of Isothermal Transformation and Cooling Transformation Diagrams*, American Society for Metals, 1997, p. 28.)



Spheroidite: Fe-C System

- **Spheroidite:**
 - α grains with spherical Fe_3C
 - diffusion dependent.
 - heat bainite or pearlite for long times
 - reduces interfacial area (driving force)




(Adapted from Fig. 10.19, *Callister, 7e.*
(Fig. 10.19 copyright United States
Steel Corporation, 1971.)


Martensite: Fe-C System

- Martensite:**


-- γ (FCC) to Martensite (BCT)
(involves single atom jumps)



- Isothermal Transf. Diagram**



Adapted from
Fig. 10.22,
Callister 7e.




Martensite needles
Austenite

(Adapted from Fig. 10.21, Callister, 7e.
(Fig. 10.21 courtesy United States
Steel Corporation.)

- γ to M transformation..
- is rapid!
- % transf. depends on T only.

Martensite Formation



M = martensite is body centered tetragonal (BCT)

Diffusionless transformation BCT if $C > 0.15$ wt%

BCT \rightarrow few slip planes \rightarrow hard, brittle




Phase Transformations of Alloys

Effect of adding other elements
Change transition temp.

Cr, Ni, Mo, Si, Mn

retard $\gamma \rightarrow \alpha + \text{Fe}_3\text{C}$
transformation




Adapted from Fig. 10.23, *Callister 7e*.



Cooling Curve

plot temp vs. time



Adapted from
Fig. 10.25,
Callister 7e.



Dynamic Phase Transformations

On the isothermal transformation diagram for 0.45 wt% C Fe-C alloy, sketch and label the time-temperature paths to produce the following microstructures:

- a) 42% proeutectoid ferrite and 58% coarse pearlite
- b) 50% fine pearlite and 50% bainite
- c) 100% martensite
- d) 50% martensite and 50% austenite




Example Problem for $C_o = 0.45 \text{ wt\%}$

a) 42% proeutectoid ferrite and 58% coarse pearlite

first make ferrite
then pearlite

course pearlite
 \therefore higher T




Example Problem for $C_o = 0.45 \text{ wt\%}$

b) 50% fine pearlite and 50% bainite

first make pearlite
then bainite


fine pearlite
 \therefore lower T

Adapted from
Fig. 10.29,
Callister 5e.



Example Problem for $C_o = 0.45 \text{ wt\%}$

- c) 100 % martensite – quench = rapid cool
- d) 50 % martensite
and 50 % austenite




Adapted from
Fig. 10.29,
Callister 5e.




Mechanical Prop: Fe-C System (1)

- Effect of wt% C

Pearlite (med)
ferrite (soft)



$C_0 < 0.76 \text{ wt\% C}$
Hypoeutectoid





Pearlite (med)
Cementite (hard)

$C_0 > 0.76 \text{ wt\% C}$
Hypereutectoid

Adapted from Fig. 9.30, Callister 7e. (Fig. 9.30 courtesy Republic Steel Corporation.)

Adapted from Fig. 9.33, Callister 7e. (Fig. 9.33 copyright 1971 by United States Steel Corporation.)





Adapted from Fig. 10.29, Callister 7e. (Fig. 10.29 based on data from *Metals Handbook: Heat Treating*, Vol. 4, 9th ed., V. Masseria (Managing Ed.), American Society for Metals, 1981, p. 9.)

- More wt% C: TS and YS increase, %EL decreases.

Mechanical Prop: Fe-C System (2)

- Fine vs coarse pearlite vs spheroidite




- Hardness: fine > coarse > spheroidite
- %RA: fine < coarse < spheroidite

Adapted from Fig. 10.30, *Callister 7e*.
(Fig. 10.30 based on data from *Metals Handbook: Heat Treating*, Vol. 4, 9th ed., V. Masseria (Managing Ed.), American Society for Metals, 1981, pp. 9 and 17.)



Mechanical Prop: Fe-C System (3)

- Fine Pearlite vs Martensite:





Adapted from Fig. 10.32, *Callister 7e*. (Fig. 10.32 adapted from Edgar C. Bain, *Functions of the Alloying Elements in Steel*, American Society for Metals, 1939, p. 36; and R.A. Grange, C.R. Hribal, and L.F. Porter, *Metall. Trans. A*, Vol. 8A, p. 1776.)

- Hardness: fine pearlite << martensite.



Tempering Martensite

- reduces brittleness of martensite,
- reduces internal stress caused by quenching.




Adapted from Fig. 10.33, Callister 7e. (Fig. 10.33 copyright by United States Steel Corporation, 1971.)

- produces extremely small Fe_3C particles surrounded by α .
- decreases TS , YS but increases $\%RA$

Summary: Processing Options

Adapted from
Fig. 10.36,
Callister 7e.



ANNOUNCEMENTS

Reading:

Core Problems:

Self-help Problems:

